

Jason Sullivan

From: Lynn Richardson [lynn.richardson@ncmail.net]
Sent: Monday, August 27, 2007 12:33 PM
To: Jason Sullivan
Subject: FW: intermittent stream characterization

Jason, please post to Harvest, sketch under Supplemental Information. Thanks, Lynn

From: Anita Bahe [mailto:abahe@earthlink.net]
Sent: Friday, August 24, 2007 2:40 PM
To: Lynn.Richardson
Cc: Nathan Wieler; Patrick Bradshaw
Subject: intermittent stream characterization

Lynn -

Another update for you I met Richard Darling with Buck Engineering (now part of Michael Baker Corporation) on the property this morning to accompany him while conducting field reconnaissance to characterize the intermittent stream that is currently shown on the USGS map at the Pea Ridge Road/Pond entrance . Richard is certified to conduct this work and is very familiar with the NCDWQ rating process. The Stream Identification Form and process outlined in the most recent "Identification Methods for the Origin of Intermittent and Perennial Streams Version 3.1, February 28, 2005" was used to conduct this assessment.

The results of this assessment indicate that there is not an intermittent stream present as shown on the USGS/Chatham GIS maps. A complete report is forthcoming from Mr. Darling next week.

If you have any questions feel free to give me a call,

Anita
Project Representative
Harvest Community, LLC

Lynx Group International, LLC
Dr. Anita R. Bahe
206 Beechtree Dr.
Cary, NC 27513
919.677.9985