

lia_myott_email.txt

Raj,

As per our recent phone conversation, I observed an ephemeral stream approximately at the location of the LIDAR blue line near stream #5 (I labeled it as D downstream on my map). The stream became an intermittent stream at a point on the northern adjacent property. Although we are currently in a drought and no water was observed in the stream channel, the presence of hydric soil (along with some geomorphological features) was a clear indication that the stream had transitioned from an ephemeral channel to an intermittent stream channel.

I did not observe the southern end of the site. Neal Floyd stated that the channel in the south (which I assume to be channel #1) was at least intermittent so it wasn't imperative that I see it. Please feel free to call me with any questions or if clarification is required (733-9502).

Regards,
Lia